## Home Technologies

## CUSTOMER SERVICE REPORT

Title Name Surname	Agreed Date of Installation	Report No.
Mrs) Elona LANGEVELDT	29/04/2005	2266
Address	Suburb 1	
4 SERRURIRA 4 SERRURIEN HVE,	MONTE VISTA	
2000 S-2004		
	Visit Technician	1
0823743790 558 3306	NO MARIO	Jaques.
Pool Size Suggested No. of Panels Pump Distance Pump Size	Type of Roof Sales Re	
6X3 5 . 75	Tiles	st
Please circle the appropriate answer to validate your warranty		
Did we arrive at the scheduled time? YES NO		
Were you greeted in a Professional manner? YES NO		
Was the installation up to Standard? Attention to neatness?	YES NO	
Did the technicians tidy up after the installation?	YES NO	
Were you shown & explained how the system works?	YES NO	
Was the system tested for 10 minutes in your presence to check for	r water leaks? YES NO	
Was a water temperature reading taken. If so what was the temp?		
What do you think about the overall installation? GOOD AVE	RAGE BELOW AVERAGE	
Would you recommend our company to your family & friends?	YES NO	
Type of payment Cheque CASH Credit Car	d Direct Bank	Fransfe.
Amount PAID & 3507.03		
Clients Signature	Hiole	
Any comments or recommendations?		The state of the s
fergued i bani g myjes en sal h aan beveel Het ve	aaf en me am bestis ilig gevoel.	de Orua.
In the event that this form cannot be filled out immediately, please fax back to	0 0866807764 when you have a moment. Tha	ink-you!